



Thermal Image Monocular
Lynx 3.0 Series (**V6.0.23 build260629**)

Release Notes

TABLE OF CONTENTS

Chapter 1 Introduction.....	0
Chapter 2 Functional Optimization	2
2.1 Fixed some bugs	2

Chapter 1 Introduction

This document introduces new features and optimizations in V6.0.23 build260629 firmware version of the products.

Version Information

Item	Description
Firmware Version	V6.0.23 build260629
Models	Lynx 3.0: LQ35 3.0, LQ35L 3.0
Mobile Client	HIKMICRO Sight V2.11.1 and above

Chapter 2 Functional Optimization

2.1 Fixed some bugs

- Fixed video playback anomaly issue
- Fixed LRF value jump after restart issue
- Fixed LRF box color and style reverting to default after restart issue

